


TRUNDLE BED CASTER ASSEMBLY



TOOLS NEEDED

1 - PHILLIPS HEAD SCREWDRIVER

PARTS LIST

A - TRUNDLE BED (1)

B - CASTER (4)

C - 1" LONG SCREW (16)

ASSEMBLY INSTRUCTIONS

1. Place trundle upside down on floor.
2. Attach four casters to blocks located on underside using (16) 1" long screws. Line up holes in casters with pilot holes bored in corner blocks.
3. Place upright and slide under bed.

THIS END UP FURNITURE CO.

P.O. Box 5410 Sanford, North Carolina 27331

(800) 605-2130 (919) 774-7474 Fax (919) 774-7430 www.thisendup.com